

# CROSS REFERENCE CHART



## CABLE, CONNECTORS, & INSTRUCTION SHEETS

AirCell <sup>®</sup> 1/2" Plenum Cable			
			8/30/11
Cable Product Code	Connector Product Code	Tool Product Code	Instruction Sheet Number
AP6012 /U50/J50 APC012 /U50/J50 AU012 /J50	NMP01250	PCT012* or PST012**	2 or 2A
	NFP01250	PCT012* or PST012**	2 or 2A
	DMP01250	PCT012* or PST012**	2 or 2A
	DFP01250	PCT012* or PST012**	2 or 2A
	NMPR01250	PCT012* or PST012**	2 or 2A
	DMPR01250	PCT012* or PST012**	2 or 2A
		TC1000 & TC10099	2B
AU012 /R50	NMP01250	PCT012	2
	NFP01250	PCT012	2
	DMP01250	PCT012	2
	DFP01250	PCT012	2
	NMPR01250	PCT012	2
	DMPR01250	PCT012	2
AP012 /U75/J75	NMP01275	PCT012 or PST012**	2 or 2A
	NFP01275	PCT012 or PST012**	2 or 2A
	PMP01275	TC1000 & TC10099	2B
	FMP01275	TC1000 & TC10099	2B
AirCell <sup>®</sup> 1/2" Plenum Radiating Cable			
Cable Product Code	Connector Product Code	Tool Product Code	Instruction Sheet Number
AQ012 /J50 AQC012 /J50	NMP01250	PST012**	2A
	NFP01250	PST012**	2A
	DMP01250	PST012**	2A
	DFP01250	PST012**	2A
	NMPR01250	PST012**	2A
	DMPR01250	PST012**	2A
		TC1000 & TC10099	2B

\*PCT = Power Tool  
\*\*PST = Manual Tool